




Mounting aid

MH 01-M12

- Suitable for M12 sensors
- Simple and fast mounting

Mounting brackets for sensors

Dimensions



Technical Data

General specifications


Inside diameter	12 mm
-----------------	-------

Mechanical specifications

Material	Clamping cylinder: Diecast zinc Support bracket: Steel
----------	---

Note	rod not included
------	------------------

Mounting



Fasten the two parts of the mounting clamp (a) loosely by means of the screw (b) and the nut (c) supplied.

Attach the mounting bracket (d) and then tighten the screw (b) in such a way that the bracket can still be turned.

Tighten the screw fully after the sensor has been mounted and aligned.